

# Mid Valley Water Well Testing LICENSE #1009816

1255 Cherry Avenue #514  
 Tulare, CA 93274  
 (559) 684 -7867  
 Midvalleypt1@gmail.com

## Well Certificate Report

### SECTION 1. CUSTOMER INFORMATION

Owner Name Richard Fite	Contact Person Richard Fite	Phone (559) 333-5242
Mailing Address 2019 E Tulare Ave	City Tulare	State CA
	Zip Code 93274	
Email Address <a href="mailto:Richardfite46@yahoo.com">Richardfite46@yahoo.com</a>		Test Date 1/11/2022

### SECTION 2. PUMP INFORMATION

Pump Location 2019 E Tulare Ave (Tulare, CA 93274)		
Latitude 36.4517	Longitude -119.2147	Meter ID # N/A
Tested By Richard Fite	Customer Type Real Estate	Water Source Well
Pump Type Submersible	Water Use Domestic	Pipe ID 2"
Motor HP 3HP	Motor Volts 230	Motor Amps 18
Motor Make Franklin	Pump Make Gulfos	Pump Name House Pump

### SECTION 3. PRODUCTIVITY TEST

Test Run	PSI	Standing Level	Pumping Level	kW Input	HP Input	Customer GPM	OPE %
Run 1	35	172'	191'	2.5	3.1	22	55%
Run 2							
Run 3							

### SECTION 4. WELL INFORMATION

RWL 173	Time 5 Minutes	Well Depth 285'
Well Diameter 8"	Well Type Steel Casing	Pump Setting 265'

### SECTION 5. RESULTS

WATER LABORATORY EXAMINATION	ENVIRONMENTAL HEALTH INSPECTION
Total Coliforms per 100ml: Absent <input type="checkbox"/> Present <input type="checkbox"/>	Bacteriologically Safe <input type="checkbox"/>
E. coli/Fecal per 100ml: Absent <input type="checkbox"/> Present <input type="checkbox"/>	Fails to Meet Standards <input type="checkbox"/>

#### NOTES:

The tester stated that the pump and well are working fine at the time of the inspection however, we can't predict the life span of the well or pump.

#### RECOMMENDATIONS:

- The pressure switch and gauge need to be replaced.
- The pump needs new air volume control.